

Final Reclamation Inspection

January 3rd, 2024

Operator: Merrion Oil and Gas Corp - 56680

Location ID: 325301

Inspection Document #: 714000301

La Plata County, CO

Township: SWNW 6 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Barnes 1
Location ID: 325301



1/3/24
+37.128692,-107.755621
236° SW

Photo 1. View of the project area taken from the eastern edge facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06119

Inspection Photos
Location Name: Barnes 1
Location ID: 325301



Photo 2. Cardinal photos taken from the center of the project area.
Left photo facing north, right photo facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06119

Inspection Photos
Location Name: Barnes 1
Location ID: 325301



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Note: fence observed in previous inspection has been removed. Project area appears consistent with surrounding grazed/prairie dog colony reference area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06119

Inspection Photos
Location Name: Barnes 1
Location ID: 325301



Photo 4. Reference area of dormant perennial grass that is also a heavily grazed area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06119