

# Final Reclamation Inspection

January 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325784

Inspection Document #: 714000302

La Plata County, CO

Township: NESE 1 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mayfield Melton 1  
Location ID: 325784



1/3/24  
+37.129829,-107.772463  
6° N



Photo 1. View of the western interim reclamation area facing north.



Inspection Photos  
Location Name: Mayfield Melton 1  
Location ID: 325784



1/3/24  
+37.129360,-107.772507  
84° E

**Photo 2.** View of the southern interim reclamation area facing east.



Inspection Photos  
Location Name: Mayfield Melton 1  
Location ID: 325784



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Reference area comprised of sagebrush, smooth brome and juniper.

API #: 067-06980