

# Final Reclamation Inspection

January 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 306916

Inspection Document #: 714000303

La Plata County, CO

Township: SWSE 1 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mayfield Melton 2  
Location ID: 306916




Photo 1. View of the disturbance from the entrance facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-09044



Inspection Photos  
Location Name: Mayfield Melton 2  
Location ID: 306916



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of the southern interim reclamation area facing east.

API #: 067-09044



Inspection Photos  
Location Name: Mayfield Melton 2  
Location ID: 306916



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of musk thistle observed along the access road.

API #: 067-09044



Inspection Photos  
Location Name: Mayfield Melton 2  
Location ID: 306916



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised of sagebrush, smooth brome and juniper.

API #: 067-09044