

# Inspection Photos

1/5/2024

**Operator:** CAERUS PICEANCE LLC #10456

**Location ID:** 334592

**Inspection Doc:** 696205505

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334592



**Photo 1:** Photos 1-3 taken from central areas of the Location. Photos examples showing areas that are not progressing towards 1004 Reclamation standards, and will require additional work.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334592



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334592



**Photo 3:** See comments under photo 1. Photo to the right taken from the access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334592



**Photo 4:** Photos 4-5 examples showing Noxious weeds observed on the Location and access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334592



**Photo 5:** See comments under photo 4.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334592



**Photo 6:** Photo example showing areas beyond the center of the Location that are progressing towards ECMC 1004 reclamation standards.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources