

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Photo 1 Multi-well pad.

Photo 2 WH/Sign.

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Photo 3 WH/Sign

Photo 4 WH/Sign.

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Photo 5 WH/Sign

Photo 6 TB location.

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Energy & Carbon Management Commission
40.14317, -104.85999, 4884.5ft, 181°
01/09/2024 15:03:26



Energy & Carbon Management Commission
40.1429, -104.86011, 4879.9ft, 204°
01/09/2024 15:04:11

Photo 7 TB/Signs

Photo 8 LACT.

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Photo 9 FWKO.

Photo 10 TB.

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Photo 11 Gas Meter Run card indicate calibration is current.

Photo 12 ECDs.

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Photo 13 Vertical Separator.



Photo 14 Horizontal Separators.

Inspection Photos
Location Name: Vollmar 29C-11HZ
Location ID: 439730



Photo 15 Horizontal Separators.

Photo 16 Compressor.