

Inspection Photos

1/5/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334617

Inspection Doc: 696205515

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



Photo 1: Photos 1-2 taken from the western working pad surface of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



January 5, 2024



January 5, 2024

Photo 3: Unused equipment



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



Photo 4: Unused container/drum/equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



Photo 5: Photos examples showing noxious weeds (musk thistle) observed established within the interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



January 5, 2024

Photo 6: See comments under photo 5.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



Photo 7: Photo taken from the slopes on the east end of the Location. Photos examples showing areas not progressing towards 1003 uniform, desirable perennial vegetative requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



Photo 8: Containment liner no longer impervious to contain a spill or release. Photos examples showing holes within liner.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334617



January 5, 2024



January 5, 2024

Photo 9: Working pad surface lacks stabilization. Tracking controls no longer in proper functioning condition. Track-out measures (such as a tracking pad) not observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources