

Inspection Photos

1/5/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334643

Inspection Doc: 696205521

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334643



January 5, 2024



January 5, 2024

Photo 1: Photos 1-2 taken from the western working pad surface of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334643



January 5, 2024

Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334643



Photo 3: Photos examples showing holes/tears within secondary containment liner.