

Inspection Photos

1/5/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 334583

Inspection Doc: 696205523

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334583



Photo 1: Photos provide an overview of the Location from southwest to northwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334583



Photo 2: Photos examples showing holes/tears within secondary containment liner.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 334583



Photo 3: Insulator hose not capped/plugged.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources