

Final Reclamation and Stormwater Inspection

Date: 01/03/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313649

Inspection Document #: 708200845

Morgan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sand River Unit 9
Location ID: 313649



Photo 1. Taken from the access road, south of the location. Photo illustrates that the access road has not been regraded or contoured to reflect adjacent reference areas, or pre-disturbance conditions. Additional reclamation activities are required.

Inspection Photos
Location Name: Sand River Unit 9
Location ID: 313649



Photo 2. Taken from the access road north of the location. See comments in Photo 1.

Inspection Photos
Location Name: Sand River Unit 9
Location ID: 313649



Photo 3. Google Earth aerial imagery taken circa 09/2023. Photo illustrates the access roads, highlighted in red, that require additional reclamation activities (e.g. contouring, regrading, revegetation, etc).

Inspection Photos
Location Name: Sand River Unit 9
Location ID: 313649



Photo 4. Taken from the eastern portion of the location, facing west. Non-uniform vegetation cover resulting in bare/exposed soils highlighted in red.

Inspection Photos
Location Name: Sand River Unit 9
Location ID: 313649




Photo 5. Taken from the western portion of the location, facing northeast. See comments in Photo 4.

Inspection Photos
Location Name: Sand River Unit 9
Location ID: 313649



Photo 6. Taken from the northern portion of the location, facing southeast. See comments in Photo 4.