

Final Reclamation and Stormwater Inspection

Date: 01/03/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313653

Inspection Document #: 708200848

Morgan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sand River 7
Location ID: 313653



Photo 1. Taken from the start of the southern access road. The access road has not been reclaimed as it has not been regraded and/or contoured to reflect adjacent reference area, or pre disturbance conditions. Red line illustrates contouring issues.

Inspection Photos
Location Name: Sand River 7
Location ID: 313653



Photo 2. The access road, east of the former well location has not been reclaimed as evidence by bare/exposed soils and contouring/grading issues.

Inspection Photos
Location Name: Sand River 7
Location ID: 313653



Photo 3. Subsidence (red circle) and bare soil (red arrow) issues at the former wellhead.

Inspection Photos
Location Name: Sand River 7
Location ID: 313653



Photo 4. The access road, north of the former well location has not been reclaimed as evidence by bare/exposed soils and contouring/grading issues.

Inspection Photos
Location Name: Sand River 7
Location ID: 313653




Photo 5. Google Earth aerial imagery (circa 09/2023) illustrates the access roads which have not been reclaimed (red arrow).