

Final Reclamation and Stormwater Inspection

Date: 01/03/2023

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313656

Inspection Document #: 708200850

Morgan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sand River #4
Location ID: 313656



Photo 1. Taken from the location entrance. Photo illustrates that the access road has not been regraded or contoured to reflect adjacent reference areas, or pre-disturbance levels.

Inspection Photos
Location Name: Sand River #4
Location ID: 313656



Photo 2. South of the former well location. It does not appear that any reclamation activities have occurred since the previous inspection. The location is still experiencing areas of non-uniform vegetation cover (bare/exposed soils) and undesirable vegetation.

Inspection Photos
Location Name: Sand River #4
Location ID: 313656



Photo 3. South end of former well location; see comments in Photo 2.

Inspection Photos
Location Name: Sand River #4
Location ID: 313656



Photo 4. North end of former well location; see comments in Photo 2.

Inspection Photos
Location Name: Sand River #4
Location ID: 313656



Photo 5. Bare soils, metal debris and undesirable vegetation (e.g. kochia and russian thistle) observed near former wellhead.

Inspection Photos
Location Name: Sand River #4
Location ID: 313656




Photo 6. Google Earth aerial imagery (circa 09/2023) illustrating the portion of the access road (red outline) that will need to be reclaimed per 1004 rules.