

Interim Reclamation and Stormwater Inspection

Date: 01/03/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313655

Inspection Document #: 708200852

Morgan County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Peterson Max #1

Location ID: 313655



Photo 1. Erosion degradation (e.g. gullyng) occurring along the access road.

Inspection Photos

Location Name: Peterson Max #1

Location ID: 313655



Photo 2. Stained soil observed at the pumpjack motor.

Inspection Photos

Location Name: Peterson Max #1

Location ID: 313655



Photo 3. Undesirable vegetation (e.g. russian thistle) was observed throughout the interim areas and will need to be managed for to prevent the spread of seed onto adjacent reference areas.

Inspection Photos

Location Name: Peterson Max #1

Location ID: 313655



Photo 4. Southern interim areas, undesirable vegetation observed; see comments in Photo 3.

Inspection Photos

Location Name: Peterson Max #1

Location ID: 313655



Photo 5. Northern interim areas, undesirable vegetation observed; see comments in Photo 3.

Inspection Photos

Location Name: Peterson Max #1

Location ID: 313655



Photo 6. North of pumpjack along the access road; see comments in Photo 3.