

# Interim Reclamation and Stormwater Inspection

Date: 01/03/2024

Operator: WESTERN OPERATING COMPANY - 95620

Location ID: 313667

Inspection Document #: 708200855

Morgan County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667



**Photo 1.** Erosion degradation occurring along the access road, with no apparent stormwater control measures observed. Additionally, vehicle traffic was observed alongside of the existing access road, in violation of Rule 1002.e.



**Photo 2.** Erosion degradation along the access road.

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667




**Photo 3.** Erosion degradation along the access road. Also pictured, vehicle traffic occurring off the existing access road.

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667



**Photo 4.** Erosion degradation along the access road.

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667



**Photo 5.** Undesirable vegetation (e.g. russian thistle and kochia) observed within the interim areas.

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667



**Photo 6.** Unstabilized soils within the interim areas.

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667



**Photo 7.** No wildlife netting observed around the secondary containment.

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667



**Photo 8.** Unused equipment within fenced portion of the location.

Inspection Photos  
Location Name: Peterson P F #1  
Location ID: 313667



**Photo 9.** Undesirable vegetation (e.g. russian thistle and kochia) observed within the interim areas.