

Inspection Photos
Location Name: Ronald Grabrian 1
Location ID: 318216



Photo 1 Wellsite location.

Photo 2 WH Sign.

Inspection Photos
Location Name: Ronald Grabrian 1
Location ID: 318216



Photo 3 Dead vegetation around the WH.

Photo 4 Dead vegetation around the WH.

Inspection Photos
Location Name: Ronald Grabrian 1
Location ID: 318216



Photo 5 Dead vegetation around the wellsite.

Photo 6 Dead vegetation around the wellsite.

Inspection Photos
Location Name: Ronald Grabrian 1
Location ID: 318216



Photo 7 Dead vegetation around the wellsite.



Photo 8 Ancillary equipment.