

Inspection Photos
Location Name: Donald M. Vynckier 2
Location ID: 318351



Photo 1 Access road to the wellsite is over run with tall dead vegetation both sides and down the middle.

Photo 2 Tall dead vegetation around the wellsite & ROW.

Inspection Photos
Location Name: Donald M. Vynckier 2
Location ID: 318351



Photo 3 Dead vegetation around the WH.

Photo 4 Dead vegetation around the WH sign.

Inspection Photos
Location Name: Donald M. Vynckier 2
Location ID: 318351



Photo 5 Dead vegetation around the wellsite.

Photo 6 Dead vegetation around the ancillary equipment.