

Inspection Photos
Location Name: Amherst Compressor Station
Facility ID Number: 427282



1. 1st Compressor.



2. 2nd Compressor.

Inspection Photos
Location Name: Amherst Compressor Station
Facility ID Number: 427282



3. Compressor inside building.



4. Steel AST.

Inspection Photos
Location Name: Amherst Compressor Station
Facility ID Number: 427282



5. Horizontal Heated Separator.Sepa



6. Additional view of processing equipment.

Inspection Photos
Location Name: Amherst Compressor Station
Facility ID Number: 427282



7. Fence line in portion of laydown yard.



8. Fence line in portion of laydown yard.

Inspection Photos
Location Name: Amherst Compressor Station
Facility ID Number: 427282



9. Fence line in portion of laydown yard.



10. Fence line in portion of laydown yard.

Inspection Photos
Location Name: Amherst Compressor Station
Facility ID Number: 427282



11. Fence line in portion of laydown yard.



12. Fence line in portion of laydown yard.