

Harris (OWP) #5
Form 27 Soil Sampling
Photographic Log
Colorado Energy & Carbon Management Commission



Photo 1: Harris (OWP) #5 well sign, 10/25/2023.




Photo 2: Harris (OWP) #5 P&A wellhead excavation, 10/25/2023.

Harris (OWP) #5
Form 27 Soil Sampling
Photographic Log

Colorado Energy & Carbon Management Commission



Photo 3: SS01 collected from Harris (OWP) #5 P&A wellhead excavation, 10/25/2023.



Photo 4: SS02 collected from former pumping unit location, 10/25/2023.

Harris (OWP) #5
Form 27 Soil Sampling
Photographic Log

Colorado Energy & Carbon Management Commission



Photo 5: SS03 collected from former meter house location, 10/25/2023.



Photo 6: Overall flowline excavation, 11/15/2023.



Photo 7: SS04 collected from former flowline excavation, 11/15/2023.



Photo 8: SS05 collected from former flowline excavation, 11/15/2023.