Inspection Photos
Location Name: HSR-LUNNON 2-3
Location ID: 320437

Photo#1 Production Tank/Produced Water Tank

Photo#2 Separator/Automation RTU

Inspection Photos
Location Name: HSR-LUNNON 2-3
Location ID: 320437

Photo#3 Wellhead