

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Photo # 2260 From entrance to location



Photo # 2261 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Jan 10, 2024 at 11:28:11 AM
CO



Jan 10, 2024 at 11:28:39 AM
CO

Photo # 2262 Location

Photo # 2263 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Photo # 2264 Location



Photo # 2265 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 89-17 Pad

Location #: 335063



Photo # 2266 Unmarked deadman



Photo # 2267 Battery sign weathered/cracking/damaged & illegible