

Operator: EXTRACTION OIL & GAS INC
Location Name: ALMQUIST MB-62N69W 34NWSE
Loc ID: 321435
Inspection: 702402810



Exhibit A

CA: Sign is peeling. Install sign to comply with Rule 605.g.

CA Resolution: Operator has replaced the signage to comply with Rule 605.g.