

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Jan 9, 2024 at 10:52:58 AM  
CO



Jan 9, 2024 at 10:53:03 AM  
CO

Photo # 2159 From entrance to location

Photo # 2160 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 2161 Location



Photo # 2162 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439




Photo # 2163 Location



Photo # 2164 Debris



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 2165 Dead weeds/debris



Photo # 2166 Dead weeds/debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



**Photo # 2167 Dead weeds/debris**



**Photo # 2168 Dead weeds/debris**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 2169 Dead weeds/debris



Photo # 2170 Dead weeds/debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 2171 Dead weeds/debris



Photo # 2172 Dead weeds/debris



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC KP 24-23 Pad

Location ID: 324439



Photo # 2173 Dead weeds/debris



Photo # 2174 Debris