

Inspection Photos
Location Name: ROUSE USX A-66N64W/5SWNW
Location #: 302562



Colorado Energy & Carbon Management Commission
Weld County
+40.516239, -104.582276
64° NE
2024-01-12 13:44

Photo #1

Rouse USX A 05-05 (123-29403) Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)



Colorado Energy & Carbon Management Commission
Weld County
+40.516443, -104.582251
77° E
2024-01-12 13:41

Photo #2

Rouse USX A 05-05 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
Site safety signage




Inspection Photos
Location Name: ROUSE USX A-66N64W/5SWNW
Location #: 302562



Colorado Energy & Carbon Management Commission
 Weld County
 +40.522267, -104.580831
 136° SE
 2024-01-12 13:18

Photo #3
Rouse USX A 05-05 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
Wellsite entrance



Colorado Energy & Carbon Management Commission
 Weld County
 +40.516133, -104.582244
 349° N
 2024-01-12 13:28

Photo #4
Rouse USX A 05-05 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: Initial plug(s)
JSA: 2024-01-12



Inspection Photos
Location Name: ROUSE USX A-66N64W/5SWNW
Location #: 302562



Photo #5

Rouse USX A 05-05 Battery site

Plugged & Abandoned | PA

Plugging Ops; Cementing: Initial plug(s)

Battery sign

