

Inspection Photos

Location Name: Wells Ranch AA 33-735 Tank Battery

Location ID: 448379



Photo 1 – ECDs



Photo 2 – Gathering Line/Pig Stations

Inspection Photos
Location Name: Wells Ranch AA 33-735 Tank Battery
Location ID: 448379



Photo 3 – West Separators and Sand Traps



Photo 4 – Middle Separator

Inspection Photos

Location Name: Wells Ranch AA 33-735 Tank Battery

Location ID: 448379



Photo 5 – Separator Open to Atmosphere



Photo 6 – Maintenance Tank

Inspection Photos
Location Name: Wells Ranch AA 33-735 Tank Battery
Location ID: 448379



Photo 7 – East Separators



Photo 8 – Compressor

Inspection Photos
Location Name: Wells Ranch AA 33-735 Tank Battery
Location ID: 448379



Photo 9 – Generators and Instrumental Air Unit

