

Inspection Photos
Location Name: Wells Ranch USX AA 27 ECONODE
Location ID: 432499



Photo 1 – Unused Secondary Containment in NE Corner of Location



Photo 2 – Instrumental Air Compressor Unit

Inspection Photos
Location Name: Wells Ranch USX AA 27 ECONODE
Location ID: 432499



Photo 3 – Compressor



Photo 4 – Generator

Inspection Photos
Location Name: Wells Ranch USX AA 27 ECONODE
Location ID: 432499



Photo 5 – Maintenance Tank



Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Wells Ranch USX AA 27 ECONODE
Location ID: 432499



Energy and Carbon Management Commission
40.45894, -104.43212, 4734.8ft
01/10/2024 14:08:33

Photo 7 – Separators and Headers

