

Final Reclamation and Stormwater Inspection

Date: 1/4/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 331920

Inspection Document #: 713900251

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: PSC 8-9
Location ID: 331920



Photo 1. The photo was taken at the start of the access road facing East. The photo illustrates some reclamation activity right along the main road with seeding rows and crimped straw.

Photo 2. The photo was taken along the access road facing Northeast. The photo illustrates the access road has not been reclaimed with gravel and tire tracks remaining.

Inspection Photos
Location Name: PSC 8-9
Location ID: 331920



Photo 3. The photo was taken at the well location facing North. The photo illustrates the location is dominated by saltgrass.



Photo 4. The photo was taken at the well location facing East. Refer to the comment for photo 3.

Inspection Photos
Location Name: PSC 8-9
Location ID: 331920



Photo 5. The photo was taken at the well location facing South.
Refer to the comment for photo 3.

Photo 6. The photo was taken at the well location facing West.
Refer to the comment for photo 3.



Photo 7. The is Google Earth imagery from 10/1999. The photo illustrates there was no access road prior to oil and gas activities.



Photo 8. The is Google Earth imagery from 05/2023. The photo illustrates the access road.