

Inspection Photos

Loc: 307975

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 1/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos




Photo 1. Facing southwest toward the wellsite.



Inspection Photos

January 16, 2024
+37.126718,-104.764101



Photo 2. Facing toward the onsite pit which is fenced.



Inspection Photos



Photo 3. Facing southwest at the location..



Inspection Photos



Photo 4. There appeared to have been a leak at meter shed.



Photo 5. The hose is not placed in the tank.

