

Final Reclamation and Stormwater Inspection

Date: 1/11/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 328213

Inspection Document #: 713900263

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bell L12-3
Location ID: 328213



Photo 1. The photo was taken at the well location facing North. The photo illustrates the northern area of the well location has been mowed.

Photo 2. The photo was taken at the well location facing East. The photo illustrates some russian thistle at the well location and that it has been mowed.

Inspection Photos
Location Name: Bell L12-3
Location ID: 328213



Colorado Energy & Carbon Management
Commission
Weld County
+40.2456,-104.7276
176° S
1/11/24, 1:21 PM



Colorado Energy & Carbon Management
Commission
Weld County
+40.2456,-104.7277
325° NW
1/11/24, 1:21 PM

Photo 3. The photo was taken at the well location facing South. The photo illustrates the well location has been mowed and appears to have been interseeded however there is still russian thistle growing at the location.

Photo 4. The photo was taken at the well location facing Northwest. Refer to the comment from photo 2.

The photo also illustrates the access road running through the well location.

Inspection Photos
Location Name: Bell L12-3
Location ID: 328213



Colorado Energy & Carbon Management
Commission
Weld County
+40.2456, -104.7277
189° S
1/11/24, 1:21 PM



Colorado Energy & Carbon Management
Commission
Weld County
+40.2432, -104.7281
141° SE
1/11/24, 1:03 PM

Photo 5. The photo was taken at the well location facing South. The photo illustrates the access road and the Southwest corner of the well location that is dominated by russian thistle.

Photo 6. The reference photo was taken near the well location facing Southeast.