

# Inspection Photos

1/17/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335636

**Inspection Doc:** 696205525

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 1:** Photo taken from the south end of the Location, facing north. Photo provides an overview of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 2:** Unused buckets with containing chemical or various equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 3:** Photos examples showing musk thistle weeds established in the interim areas of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335636



**Photo 4:** Armored ditch and sediment trap on north end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources