

Inspection Photos

1/17/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743

Inspection Doc: 696205527

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



Photo 1: Photos taken from the north end of the Location. Photos provide an overview of the Location from south and southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



Photo 2: Signage at tank battery missing required well API information.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



Photo 3: Erosion degradation developing along access road.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



Photo 4: Photo taken from the east end of the Location. Photo shows BMPs to manage runoff are inadequate, resulting in erosion degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



Photo 5: Photos examples showing BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation or off-site sediment transport are missing or insufficient; WPS lacks stabilization.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



Photo 6: Unused sign, post and plastic trash.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335743



Photo 7: Photo taken from the interim areas. Limited inspection due to snow cover; desirable plant establishment is evident; interim areas appear to be progressing towards 1003 standards.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources