

Inspection Photos

1/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335637

Inspection Doc: 696205529

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335637



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335637



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335637



January 16, 2024

Photo 3: Photo example of vegetation establishment over the interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335637



Photo 4: Cellar at well API 045-06486. Cellar has not been backfilled or covered; BMPs to minimize wildlife ingress or egress are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources