

Inspection Photos

1/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663

Inspection Doc: 696205531

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 1: Photos taken from the south end of the Location. Photos provide an overview of the Location from north and northeast



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 2: Photos examples show erosion degradation (tracking, ruts). BMPs to stabilize the working pad surface, and to minimize erosion, degradation and sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 3: Photos examples show erosion degradation (tracking, ruts). BMPs to stabilize the working pad surface, and to minimize erosion, degradation and sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 4: Photo taken from the stormwater ditch on the north end of the Location. Photo shows the stormwater has diverted around the rock-check dam resulting in degradation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 5: Fence in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 6: Photo example of trash debris observed in the interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



January 16, 2024

Photo 7: Unused gate panel improperly stored on Location. Unused equipment requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 311663



Photo 8: Photo example of anchors missing required marking.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources