

Inspection Photos

1/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777

Inspection Doc: 696205533

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



Photo 1: Photos taken from the east end of the Location. Photos provide an overview of the Location from southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



Photo 2: Photos taken from the east end of the Location; erosion degradation evident along slopes. BMPs to minimize erosion, degradation and sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



January 16, 2024



January 16, 2024

Photo 3: Photos examples show erosion degradation (tracking, ruts). BMPs to stabilize the working pad surface, and to minimize erosion, degradation and sediment transport are missing or insufficient.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335777



Photo 4: Fence at wells in disrepair.