



00066979

WELL SITE INSPECTION FORM

087-5775
10-26-92 PA-4LOCATION SW SW 10-2N-55WFIELD ZORICHAKOPERATOR CONRADCOUNTY MORGANWELL NAME ATKINSON #1

PERMIT # _____

DATE OF INSPECTION DURING DRILLING: _____

RIG _____ SURFACE CASING: _____ DEPTH: _____
BOP'S _____ RETURNS: _____ WOC: _____
CONTACT _____ CMT VOL: _____
ADEQUATE AQUIFER PROTECTION? _____
COMMENTS _____

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: YES _____ NO _____ PRODUCTION STRING: _____
WATER DISPOSAL: PITS _____, INJECTED _____, COMMERCIAL _____, UNKNOWN _____, N.A. _____
PITS: PERMIT Y _____ N _____, SKIM TANK Y _____ N _____, DIMENSIONS _____
LEASE SIGN: YES _____ NO _____ TANK ID: YES _____ NO _____ NA _____ FENCED: YES _____ NO _____
SURFACE EQUIPMENT: _____
COMMENTS: _____

DATE OF P&A INSPECTION 10/22/86

PITS BACKFILLED: YES ☒ NO _____ SURFACE RECLAIMED: YES ☒ NO _____
HOLE MARKER: YES _____ NO ☒ SITE CLEAN: YES ☒ NO _____
BOND RELEASE OK: YES ☒ NO _____ LANDOWNER RELEASE: YES _____ NO _____

COMMENTS: 1' OF FLOW LINE ABOVE GROUND TO MARK SITE - OTHERWISE GOOD
RESTORATION - CATTLE PASTURE SO WILL ACCEPT THIS AS OK
INSPECTION WAS A RESULT OF DOING PIT INSPECTIONS. THIS WELL SITE WAS
LISTED AS STILL BEING A PRODUCER.
DATE OF SAFETY INSPECTION _____

COMMENTS: Will Have To Pull FKE + INVESTIGATE

INSPECTOR JSKAPI No. 05-087-0 ?P&A Inspected: Yes ☒ No _____