

Inspection Photos

Location Name: CAERUS PICEANCE LLC, TEXACO FEE-66S99W/27SENW

Location ID: 323873

Date: 1/16/2024



Jan 16, 2024 at 14:26:46



Jan 16, 2024 at 14:27:36

Location Entrance – Photo #08690


Wellhead – Photo #08692

Inspection Photos

Location Name: CAERUS PICEANCE LLC, TEXACO FEE-66S99W/27SENW

Location ID: 323873

Date: 1/16/2024



Separator – Photo #08691



Tank Battery/No Battery Sign – Photo #08693