

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
BRATTAIN L 12-03JI (2023 Seasonal)	Spring	Gage Hesse	5/16/2023

Work Summary	Reclamation Type	Land Use
Inter seeded location	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance	Normal	No	Location(s): BRATTAIN L 12-3JI Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **87,120 sq ft**
 Seed Mix: **Sandy Soil 2 (30.00 lbs)**
 Crop Type:
 Soil Type: **Sandy**
 Stabilization Date: **5/16/2023**
 Seeding Date: **5/16/2023**
 Mulch: **None**
 Straw Bales: **NA**
 Soil Amendment Type: **None**
 Soil Amendment Rate: **NA**
 Imported Top Soil: **NA**
 Top Soil Source: **NA**
 General Notes: **Rm 625**

LOCATION INFO

Location(s) – Name: BRATTAIN L 12-3JI

COGCC ID: **331907**

Well APIs at Location: **12321547**

Land Rep: **David Bell**

Land Owner: **KMG**

Rec Contractor PO(s): **H2 PO:4501185318**

Vendor PO(s): **Buffalo Brand Seed PO:4501213682**

Billing Notes: **O21-14391.01.10**

Legal Address: **(WELD) NENW 12 3N66W**

Topsoil Source:

Variance Notes:

Private Utility Notes: **cleared**

Wildlife Restrictions: **Cleared**

General Notes: **Rm 625**

COGCC Doc #'s:

Initial Reclaim Complete Date:

Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Seed Mix

Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:

