

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
BRATTAIN L 12-03JI (2023 Seasonal)	Fall	Marco Gonzalez	9/21/2023
Work Summary	Reclamation Type	Land Use	
Innerseeded location	Final Maint	Other	
One-Call Number	Red Zone Rep	Red Zone Date	

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance	Normal	No	Location(s): BRATTAIN L 12-3JI Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **43,560 sq ft**
Seed Mix: **Sandy Soil 2 (15.00 lbs)**
Crop Type:
Soil Type: **Sandy**
Stabilization Date:
Seeding Date: **9/21/2023**
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes: **Job rm 625**

LOCATION INFO

Location(s) – Name: BRATTAIN L 12-3JI

COGCC ID: **331907**
Well APIs at Location: **12321547**
Land Rep: **David Bell**
Land Owner: **KMG**
Rec Contractor PO(s): **H2 PO:4501185318**
Vendor PO(s): **Buffalo Brand Seed PO:4501213682**
Billing Notes: **O21-14391.01.10**
Legal Address: **(WELD) NENW 12 3N66W**
Topsoil Source:
Variance Notes:
Private Utility Notes: **cleared**
Wildlife Restrictions: **Cleared**
General Notes: **Job rm 625**
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map
Description:




Photo Name: Seed Mix

Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:

