

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
BELL L 12-03 (2023 Seasonal)	Spring	Gage Hesse	5/16/2023

Work Summary	Reclamation Type	Land Use
Inter seeded location	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance	Normal	No	Location(s): BELL L 12-03 Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: **108,900 sq ft**
 Seed Mix: **Sandy Soil 2 (37.50 lbs)**
 Crop Type:
 Soil Type: **Sandy**
 Stabilization Date: **5/16/2023**
 Seeding Date: **5/16/2023**
 Mulch: **None**
 Straw Bales: **NA**
 Soil Amendment Type: **None**
 Soil Amendment Rate: **NA**
 Imported Top Soil: **NA**
 Top Soil Source: **NA**
 General Notes: **Rm034**

LOCATION INFO

Location(s) – Name: BELL L 12-03

COGCC ID: **328213**
Well APIs at Location: **12315705**
Land Rep: **jobe**
Land Owner:
Rec Contractor PO(s): **H2 PO:4501168051**
Vendor PO(s): **Buffalo Brand Seed PO:4501173751**
Billing Notes: **O22-00638.01.10**
Legal Address: **(WELD) NENW 12 3N66W**
Topsoil Source:
Variance Notes:
Private Utility Notes:
Wildlife Restrictions:
General Notes: **Rm034**
COGCC Doc #'s:
Initial Reclaim Complete Date:
Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Seed Mix
Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:

