

Work Completion Report

Contractor: H2 Enterprises (H2)

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
BELL L 12-03 (2023 Seasonal)	Summer	Dakota Kling	8/21/2023

Work Summary	Reclamation Type	Land Use
Mowed weeds in work area.	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Final Reclamation Maintenance	Normal	No	Location(s): BELL L 12-03 Notes: May include innerseeding, mowing, spraying, debris clean-up. If locates and red zone are required, please notify Oxy to modify job assignment and schedule on-site meeting. If the location does not need work completed, please complete a work completion report. If location is ready for Form 4, please complete inspection and add Form 4 work task

COMPLETION DETAILS

Total Area Affected: <b>21,780 sq ft</b> Seed Mix: <b>None used</b> Crop Type: Soil Type: <b>Sandy</b> Stabilization Date: Seeding Date: Mulch: <b>None</b> Straw Bales: <b>NA</b> Soil Amendment Type: <b>None</b> Soil Amendment Rate: <b>NA</b> Imported Top Soil: <b>NA</b> Top Soil Source: <b>NA</b> General Notes:
---

## LOCATION INFO

---

### Location(s) – Name: BELL L 12-03

COGCC ID: **328213**

Well APIs at Location: **12315705**

Land Rep: **jobe**

Land Owner:

Rec Contractor PO(s): **H2 PO:4501168051**

Vendor PO(s): **Buffalo Brand Seed PO:4501173751**

Billing Notes: **O22-00638.01.10**

Legal Address: **(WELD) NENW 12 3N66W**

Topsoil Source:

Variance Notes:

Private Utility Notes:

Wildlife Restrictions:


General Notes:

COGCC Doc #'s:

Initial Reclaim Complete Date:

Maint. Reclaim Complete Date:

PHOTOS



**Photo Name: Pre-Completion**

Description:





**Photo Name: Post-Completion**

Description:



**Photo Name: Before 1**

Description:





Photo Name: Before 2

Description:





Photo Name: Before 3

Description:





Photo Name: After 1  
Description:



Photo Name: After 2

Description:

