

Operator: EXTRACTION OIL & GAS INC
Location Name: KILKER-61S69W 15SENE
Loc ID: 321372
Inspection: 699505277



Exhibit A

CA: Stained soil near tank see pictures. Properly dispose of oily waste in accordance with 905.e.

CA Resolution: Operator adequately addressed and disposed of the identified stained soil to comply with Rule 905.e.