

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/17/2024

Submitted Date:

01/17/2024

Document Number:

701007976

FIELD INSPECTION FORM

Loc ID 314216 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10227
Name of Operator: CHOLLA PETROLEUM INC
Address: PO BOX 12208
City: DALLAS State: TX Zip: 75225

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Obenchain, Tom	214-455-4614	tao@chollapetro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278882	WELL	PR	10/01/2023	GW	099-06885	MAGIWA UNIT 1-23	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at solar panels. Sticker is peeling off		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	02/17/2024
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank are faded and need replaced		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	02/17/2024

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Wire panels around solar panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire panels around water tank		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Wire panels around HGS and meter run		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 278882 Type: WELL API Number: 099-06885 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT