

# Inspection Photos

1/16/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335453

**Inspection Doc:** 696205537

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335453



**Photo 1:** Photos taken from the northern working pad surface of the Location. Photos provide an overview of the Location from southeast to southwest. Photos also examples showing BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation and off-site sediment transport are missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335453



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources