

# Inspection Photos

1/16/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 335571

**Inspection Doc:** 696205541

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335571



**Photo 1:** Photos taken from the west interim areas of the Location. Photos provide an overview of the Location and interim areas from north, northeast, southeast to south.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335571



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335571



**Photo 3:** Photos examples showing additional reclamation has been performed. Photo right example showing areas of dense mulch accumulation. Excess mulch may hinder the reclamation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335571



**Photo 4:** Rutting due to equipment during reclamation efforts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335571



January 16, 2024

**Photo 5:** Photo example showing additional reclamation efforts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources