

Inspection Photos

1/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322432

Inspection Doc: 696205543

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322432



Photo 1: Photos taken from the west end of the working pad surface. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322432



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322432



Photo 3: Photos examples showing additional reclamation has been performed. Photo right example showing areas of dense mulch accumulation. Excess mulch may hinder the reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322432



Photo 4: Rutting due to equipment during reclamation efforts.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 322432



Photo 5: Photo example showing additional reclamation efforts.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources