

Inspection Photos

1/16/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324180

Inspection Doc: 696205545

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324180



Photo 1: Photos taken from the west end of the working pad surface. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324180



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324180



Photo 3: Photos examples showing BMPs to stabilize the working pad surface and access road are not longer in proper functioning condition; control measures to minimize tracking inadequate; control measures to minimize off-site sediment transport by equipment, such as a vehicle tracking pad, also not observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources