

Interim and Stormwater Inspection

January 10, 2023

Operator: PDC Energy- #69175

Location ID: 459907

Inspection Document #: 709400721

Adams County, CO

SWNW Section 21 T1S R67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Tower pad & Tank Battery
Facility ID: 459907



Photo 1. Photo taken of location sign at entrance, facing northeast.



Photo 2. Photo taken of wellhead. Photo taken facing southwest..



Inspection Photos
Location Name: Tower pad & Tank Battery
Facility ID: 459907



Jan 10, 2024 at 9:57:28 AM
Thornton CO 80602
United States

Photo 3. Photo taken of stormwater erosion at entrance of pad.
Photo taken facing south.



Jan 10, 2024 at 9:59:48 AM
Thornton CO 80602
United States

Photo 4. Photo taken of weeds (kochia & russian thistle) on site.
Photo taken facing west.



Inspection Photos
Location Name: Tower pad & Tank Battery
Facility ID: 459907



Photo 5. Photo taken of weeds (kochia) in vegetated area between tank battery and wellheads. Photo taken facing south.



Photo 6. Photo of sediment filled wattle check dam in drainage on south side of location. . Photo taken facing east

Inspection Photos
Location Name: Tower pad & Tank Battery
Facility ID: 459907



Photo 7. Photo taken of reclaimed area on southside of location. . Photo taken facing east.



Photo 8. Photo taken of erosion from stormwater on the southside of access road into location.. Photo taken facing east.