

Interim and Stormwater Inspection

January 10,, 2023

Operator: KP Kauffman Company- #46290

Location ID: 427862

Inspection Document #: 709400724

Adams County, CO

SESW Section 8 T1S R67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Brown 11-8 &
Tank Battery
Facility ID: 427862



Photo 1. Photo taken of location sign at tank battery, facing northwest.



Photo 2. Photo taken of Wellheads. Photo taken facing east.



Inspection Photos
Location Name: Brown 11-8 &
Tank Battery
Facility ID: 427862



Photo 3. Photo taken of weeds (kochia) around wellheads..
Photo taken facing east.



Photo 4. Photo taken of weeds (kochia) around wellheads..
Photo taken facing south.

Inspection Photos
Location Name: Brown 11-8 &
Tank Battery
Facility ID: 427862



Photo 5. Photo taken of tank battery on pad. Photo taken facing southwest.



Photo 6. Photo of access road and weeds (kochia & russian thistle) leading to pumpjack and tank battery. Photo taken facing south.