

Interim and Stormwater Inspection

January 10, 2024

Operator: KP Kauffman Company- #46290

Location ID: 333088

Inspection Document #: 709400726

Adams County, CO

NESW Section 7 T1S R67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: StoneHocker 23-7
Facility ID: 333088



Photo 1. Photo taken of location sign, facing north.



Photo 2. Photo taken of excavation where tank battery once was. Photo taken facing east.



Inspection Photos
Location Name: StoneHocker 23-7
Facility ID: 333088



Photo 3. Photo taken of weeds (kochia) around excavation. Photo taken facing northeast.



Photo 4. Photo taken of unsecure fencing blowing in the wind. Photo taken facing east.

Inspection Photos
Location Name: StoneHocker 23-7
Facility ID: 333088



Photo 5. Photo taken of weeds on site around excavation. Photo taken facing northeast.



Photo 6. Photo of down fencing on north side of excavation. Photo taken facing east.

Inspection Photos
Location Name: StoneHocker 23-7
Facility ID: 333088



Photo 7. Photo taken of unused equipment on site.. Photo taken facing east.



Photo 8. Photo of open excavation filled with weed debris and inadequate fencing. Photo taken facing east.