

Interim and Stormwater Inspection

January 10, 2024

Operator: McClane Energy Inc.- #10602

Location ID: 320135

Inspection Document #: 709400728

Adams County, CO

SWSW Section 23 T1S R67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Van Scoyk 1
Facility ID: 320135



Photo 1. Photo taken of location sign, facing northwest.




Photo 2. Photo taken of tank battery and weeds (kochia & Russian thistle) Photo taken facing north.



Inspection Photos
Location Name: Van Scoyk 1
Facility ID: 320135



Photo 3. Photo taken of weeds (kochia) around equipment and tanks. Photo taken facing northeast.



Photo 4. Photo taken of weeds kochia & Russian thistle). Photo taken facing east.

Inspection Photos
Location Name: Van Scoyk 1
Facility ID: 320135



Jan 10, 2024 at 11:04:40 AM
10049-10899 E 136th Ave
Brighton CO 80602
United States

Photo 5. Photo taken of weeds on site around equipment. Photo taken facing northeast.



Jan 10, 2024 at 11:05:10 AM
10049-10899 E 136th Ave
Brighton CO 80602
United States

Photo 6. Photo of harvested crop field around location. Photo taken facing northeast.

