

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 24-28 Pad

Location ID: 335406



Photo # 3177 From entrance to location



Photo # 3178 From entrance to location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 24-28 Pad

Location ID: 335406




Photo # 3179 Location



Photo # 3180 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 24-28 Pad

Location ID: 335406



Photo # 3181 Location



Photo # 3182 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 24-28 Pad

Location ID: 335406



**Photo # 3183 Open ended pipping on separator unit/wildlife hazard**



**Photo # 3184**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 24-28 Pad

Location ID: 335406



Photo # 3185 Improperly marked deadman