

Final Reclamation Inspection

January 17th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325649

Inspection Document #: 714000317

La Plata County, CO

Township: SWNE 1 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Angelina 5
Location ID: 325649



1/17/24
+37.135133,-108.098772
306° NW



1/17/24
+37.135230,-108.098779
257° W

Photo 1. View of the disturbance from the entrance facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06771

Inspection Photos
Location Name: Angelina 5
Location ID: 325649

1/17/24
+37.135309,-108.098842
130° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Interim vegetation was not fully assessed due to snowy conditions.

API #: 067-06771